



NO.01



NO.02

Please check above pictures. This is VITON sleeved in NO.01, That is VITON seat with backed in No.02.

There is no any back between body and seat, It is necessary to the machining accuracy of precision both the body and the disc, and the disc processing must be after the seat assembled on the body and then measure the dimension of the disc. It is normal to need more time than No,02, Meanwhile it also increase the processing difficulty.For these two pieces of samples, General the delivery time is under our control.But some of the accident is not what we can control Such as casting, machining, painting,etc.

There is with back between body and seat in No.02.The production of body, disc, seat and others processing can be simultaneously, it save more time than No.01.

Now the delivery time will be delayed about 2 days,Pressure test could only achieve 15Bar when our workers inspected the valves in the afternoon of today due to the dimension of original disc was smaller a little, We arranged production schedule to processing new disc when we got the test results.

As a responsible manufacturer, we have to provide the qualified product to you.We can't in order to catch the delivery date and ignore the product quality. It is also the foundation of cooperation that we have to give the true feedback for progressing of the order to you. We're so sorry for the delay, pls understand this.Many thanks!